

MITSUBISHI HEAVY INDUSTRIES AMERICA INC.

MITSUBISHI SERVICE PUBLICATIONS TRANSMITTAL

The attached Mitsubishi MU-2B series Service Publication has been issued by Mitsubishi Heavy Industries, Ltd. in Japan, who is the type certificate holder of the MU-2 aircraft. It is the owner and/or operator's responsibility to adhere to or comply with new information contained in the attached publication.

SN 130 Rev.B MU-2 Technical Manual Index

Export Control

These items are controlled by the U.S. Government and authorized for export only to the country of ultimate destination for use by the ultimate consignee or end-user(s) herein identified. They may not be resold, transferred, or otherwise disposed of, to any other country or to any person other than the authorized ultimate consignee or end-user(s), either in their original form or after being incorporated into other items, without first obtaining approval from the U.S. government or as otherwise authorized by U.S. law and regulations.

ECCN: 9E991

NOTE

THIS PUBLICATION IS PRINTED AND/OR DISTRIBUTED BY MITSUBISHI HEAVY INDUSTRIES AMERICA, INC., UNDER LICENSE FROM MITSUBISHI HEAVY INDUSTRIES LTD. FOR COMMENTS OR INQUIRIES REGARDING DISTRIBUTION OF THIS PUBLICATION OR RECEIPT OF ANY OF THE PUBLICATIONS LISTED HEREIN, PLEASE CONTACT:

Mitsubishi Heavy Industries America, Inc.
Aircraft Product Support Division
450 N. Freeport Pkwy Suite 3400 Coppell, TX 75019
USA

Email: mu-2support@mhia.com

THIS PAGE INTENTIONALLY LEFT BLANK



MU-2

SERVICE NEWS

MITSUBISHI HEAVY INDUSTRIES, LTD.
NAGOYA AEROSPACE SYSTEMS WORKS
10, OYE-CHO, MINATO-KU, NAGOYA, AICHI, JAPAN

DATE: May 1, 2026

REVISION SHEET

This sheet transmits REVISION "B" of the following SERVICE NEWS.

MU-2 SERVICE NEWS

Number: 130B
Subject: MU-2 Technical Manual Index
Previous Revision: A

REVISION PAGES

Information revised or added in this revision is identified with the letter R in the right-hand margin.

This revision is to update current revisions and additions which have been issued since the last revision date of this Service News through April 30, 2026.

This list is reprinted in its entirety. Please remove and discard all pages of previous issues and replace with this revision B, dated May 1, 2026.



MU-2

SERVICE NEWS

MITSUBISHI HEAVY INDUSTRIES, LTD.
NAGOYA AEROSPACE SYSTEMS WORKS
10, OYE-CHO, MINATO-KU, NAGOYA, AICHI, JAPAN

JCAB T.C.: No. 130B

DATE: May 1, 2026

SUBJECT – MU-2 Technical Manual Index

MODELS AFFECTED – MU-2B/-10/-15/-20/-25/-26

S/N 008 through 347 (except S/N 313, 321)

MU-2B-30/-35/-36

S/N 501 through 696 (except S/N 652, 661)

PURPOSE – To provide applicable MU-2 owner/operators and other interested parties with a list of current MU-2 technical manuals and revision status.

INTRODUCTION

This Service News provides a listing of MU-2 technical manuals for airplanes manufactured under JCAB Type Certificate (A2PC) and for airplanes with JCAB Supplemental Type Certificates incorporated.

The listing consists of;

- Airplane Flight Manuals
- Pilot Checklist
- Pilot's Operating Manuals
- Maintenance Manuals
- Wiring Diagram Manuals
- Aircraft Inspection and Maintenance Requirements Manuals
- Structural Repair Manuals
- Parts Catalogs

MU-2 Service News

JCAB T.C.: No. 130B

DATE: May 1, 2026

Issuance and Revision

- A. This list shall be issued to all applicable owner/operators and other interested parties. This list is accurate as of the date of issue, but later revisions may be made to any of these manuals. If a discrepancy exists between this list and any manual, a later revision to that manual takes precedence.
- B. This Service News will be revised periodically to provide current status concerning all MU-2 technical manuals. The revised list may include the affected page(s) or a complete new list. It is the owner/operator's responsibility to maintain the list by adding or replacing the page(s) as necessary.
- C. Revision Letter
 - (1) Additions, deletions, or revisions will be identified by the letter R in the right-hand margin adjacent to the change.
 - (2) When a new page is added, the letter R shall appear in the left-hand margin adjacent to the page number and date.
- D. Printing and Distribution

All publications will be printed and/or distributed by Mitsubishi Heavy Industries America, Inc. under license from Mitsubishi Heavy Industries, Ltd. For comments or inquiries regarding contents of MU-2 Service Information, distribution of this publication or receipt of any of the publications listed herein, please contact:

Mitsubishi Heavy Industries America, Inc.
Aircraft Product Support Division
450 North Freeport, Suite 3400
Coppell, Texas 75019
U.S.A.

mu-2support@mhia.com

R
R

R

MU-2 Service News

JCAB T.C.: No. 130B

DATE: May 1, 2026

E. Publication Availability

R

All MU-2 publications listed in this Service News are available from Veryon on an annual subscription basis. Veryon can be reached at 548 Market Street, Suite 42403, San Francisco, California 94104, Tel: +1-800-747-4560, Email: learnmore@veryon.com, Web: veryon.com.

R

R

R

R

Only Airplane Flight Manuals, Pilot's Operating Manuals and FAA Accepted Pilot Checklists are available for sale from MHIA. Airplane Flight Manuals and Pilots Operating Manuals will be delivered together as a package and never sold separately.

R

R

R

For any questions related to MU-2 Technical Publications, please contact Mitsubishi Heavy Industries America, Inc. (MHIA):

R

R

Mitsubishi Heavy Industries America, Inc.

R

Aircraft Product Support Division

R

450 N. Freeport Pkwy, Suite 3400

R

Coppell, Texas 75019

R

Email: mu-2support@mhia.com

R

Web: www.mu-2aircraft.com

R

MU-2 Service News

JCAB T.C.: No. 130B

DATE: May 1, 2026

R

Document: Airplane Flight Manual (AFM)

Doc#	Manual	Effective Model	Approval	Original/ Reissue Date	Latest		Subject
					Rev.	Issue Date	
YET 67026A	AFM	MU-2B	JCAB	03/05/1987	15	09/28/2021	MU-2B AIRPLANE FLIGHT MANUAL
	AFM Supplement 1	MU-2B	JCAB	03/05/1987	1	12/21/1992	KING RADIO CORP. OR MINNEAPOLIS HONEYWELL REGULATOR CO. MODEL H-14 ADAPTIVE AUTOPILOT SYSTEM (D/C No. 0355)
	AFM Supplement, Code No. C3	MU-2B/-10	FAA	01/12/1988	1	05/11/1993	BENDIX MODEL M-4C AUTOMATIC FLIGHT CONTROL SYSTEM (STC No. SA1310WE, SB 066/22-006)
	AFM Supplement 2	MU-2B	JCAB	10/20/1992	-	-	ROSEMOUNT MODEL 871CT1 SUPPLEMENTARY ICE DETECTION SYSTEM (D/A No. 0253, SB 217)
	AFM Supplement 3	MU-2B	JCAB	06/30/1997	-	-	TRIM-IN-MOTION ALERT SYSTEM (D/A No. 0256, SB 231)
	AFM Supplement 4	MU-2B	JCAB	06/30/1997	-	-	AUTOMATIC AUTOPILOT DISCONNECT SYSTEM (D/A No. 0257, SB 231)
	AFM Supplement 5	MU-2B	JCAB	06/03/1997	-	-	PNEUMATIC DE-ICE MONITORING SYSTEM (D/A No. 0258, SB 232)
YET 86400	AFM	MU-2B-10	JCAB	03/05/1987	13	11/29/2007	MU-2B-10 AIRPLANE FLIGHT MANUAL
	AFM Supplement 1	MU-2B-10	JCAB	03/05/1987	1	12/21/1992	KING RADIO CORP. OR MINNEAPOLIS HONEYWELL REGULATOR CO. MODEL H-14 ADAPTIVE AUTOPILOT SYSTEM (D/C No. 0355)
	AFM Supplement, Code No. C3	MU-2B/-10	FAA	01/12/1988	1	05/11/1993	BENDIX MODEL M-4C AUTOMATIC FLIGHT CONTROL SYSTEM (STC No. SA955SW, SB 066/22-006)
	AFM Supplement 2	MU-2B-10	JCAB	10/20/1992	-	-	ROSEMOUNT MODEL 871CT1 SUPPLEMENTARY ICE DETECTION SYSTEM (D/A No. 0253, SB 217)
	AFM Supplement 3	MU-2B-10	JCAB	06/30/1997	-	-	TRIM-IN-MOTION ALERT SYSTEM (D/A No. 0256, SB 231)
	AFM Supplement 4	MU-2B-10	JCAB	06/30/1997	-	-	AUTOMATIC AUTOPILOT DISCONNECT SYSTEM (D/A No. 0257, SB 231)
	AFM Supplement 5	MU-2B-10	JCAB	06/30/1997	-	-	PNEUMATIC DE-ICE MONITORING SYSTEM (D/A No. 0258, SB 232)

MU-2 Service News

JCAB T.C.: No. 130B

DATE: May 1, 2026

Document: Airplane Flight Manual (AFM)

Doc#	Manual	Effective Model	Approval	Original/ Reissue Date	Latest		Subject
					Rev.	Issue Date	
YET 68038A	AFM	MU-2B-15	JCAB	03/05/1987	13	11/29/2007	MU-2B-15 AIRPLANE FLIGHT MANUAL
	AFM Supplement 1	MU-2B-15	JCAB	03/05/1987	1	12/21/1992	KING RADIO CORP. OR MINNEAPOLIS HONEYWELL REGULATOR CO. MODEL H-14 ADAPTIVE AUTOPILOT SYSTEM (D/C No. 0355)
	AFM Supplement, Code No. C2	MU-2B-15/-20/-25	FAA	01/12/1988	1	05/11/1993	BENDIX MODEL M-4C AUTOMATIC FLIGHT CONTROL SYSTEM (STC No.SA955SW, SB 066/22-006)
	AFM Supplement, Code No. T7	MU-2B-15/-20	FAA	01/12/1988	-	-	BENDIX MANUAL ELECTRIC PITCH TRIM SYSTEM (STC No.SA1354SW, SB 066/22-006)
	AFM Supplement 2	MU-2B-15	JCAB	10/20/1992	-	-	ROSEMOUNT MODEL 871CTI SUPPLEMENTARY ICE DETECTION SYSTEM (D/A No. 0253, SB 217)
	AFM Supplement 3	MU-2B-15	JCAB	06/30/1997	-	-	TRIM-IN-MOTION ALERT SYSTEM (D/A No. 0256, SB 231)
	AFM Supplement 4	MU-2B-15	JCAB	06/30/1997	-	-	AUTOMATIC AUTOPILOT DISCONNECT SYSTEM (D/A No. 0257,SB 231)
	AFM Supplement 5	MU-2B-15	JCAB	06/30/1997	-	-	PNEUMATIC DE-ICE MONITORING SYSTEM (D/A No. 0258, SB 232)
YET 68034A	AFM	MU-2B-20	JCAB	03/03/1987	15	09/28/2021	MU-2B-20 AIRPLANE FLIGHT MANUAL
	AFM Supplement 1	MU-2B-20	JCAB	03/05/1987	1	12/21/1992	KING RADIO CORP. OR MINNEAPOLIS HONEYWELL REGULATOR CO. MODEL H-14 ADAPTIVE AUTOPILOT SYSTEM (D/C No. 0355)
	AFM Supplement 2	MU-2B-20	JCAB	03/03/1987	-	-	STROBE LIGHT
	AFM Supplement 3	MU-2B-20	JCAB	03/03/1987	-	-	WOODWARD PROPELLER SYNCHRONIZER SYSTEM
	AFM Supplement 4	MU-2B-20	JCAB	03/03/1987	1	05/10/1988	ELECTRIC PITCH TRIM SYSTEM (D/C No. 0332)
	AFM Supplement, Code No. C2	MU-2B-15/-20/-25	FAA	01/12/1988	1	05/11/1993	BENDIX MODEL M-4C AUTOMATIC FLIGHT CONTROL SYSTEM (STC No.SA955SW, SB 066/22-006)

R

MU-2 Service News

JCAB T.C.: No. 130B

DATE: May 1, 2026

R

Document: Airplane Flight Manual (AFM)

Doc#	Manual	Effective Model	Approval	Original/ Reissue Date	Latest		Subject
					Rev.	Issue Date	
	AFM Supplement, Code No. T7	MU-2B-15/-20	FAA	01/12/1988	-	-	BENDIX MANUAL ELECTRIC PITCH TRIM SYSTEM (STC No.SA1354SW, SB 066/22-006)
	AFM Supplement 5	MU-2B-20	JCAB	10/20/1992	-	-	ROSEMOUNT MODEL 871CT1 SUPPLEMENTARY ICE DETECTION SYSTEM (D/A No. 0253, SB 217)
	AFM Supplement 6	MU-2B-20	JCAB	06/30/1997	-	-	TRIM-IN-MOTION ALERT SYSTEM (D/A No. 0256, SB 231)
	AFM Supplement 7	MU-2B-20	JCAB	06/30/1997	-	-	AUTOMATIC AUTOPILOT DISCONNECT SYSTEM (D/A No. 0257, SB 231)
	AFM Supplement 8	MU-2B-20	JCAB	06/30/1997	-	-	PNEUMATIC DE-ICE MONITORING SYSTEM (D/A No. 0258, SB 232)
YET 71367A	AFM	MU-2B-25	JCAB	03/03/1987	15	09/28/2021	MU-2B-25 AIRPLANE FLIGHT MANUAL
	AFM Supplement 1	MU-2B-25	JCAB	03/05/1987	1	12/21/1992	KING RADIO CORP. OR MINNEAPOLIS HONEYWELL REGULATOR CO. MODEL H-14 ADAPTIVE AUTOPILOT SYSTEM (D/C No. 0355)
	AFM Supplement 2	MU-2B-25	JCAB	03/03/1987	1	05/10/1988	ELECTRIC PITCH TRIM SYSTEM (D/C No. 0332)
	AFM Supplement 3	MU-2B-25	JCAB	03/03/1987	-	-	STROBE LIGHT
	AFM Supplement 4	MU-2B-25	JCAB	03/03/1987	-	-	WOODWARD PROPELLER SYNCHRONIZER SYSTEM
	AFM Supplement 5	MU-2B-25	JCAB	10/20/1992	-	-	ROSEMOUNT MODEL 871CT1 SUPPLEMENTARY ICE DETECTION SYSTEM (D/A No. 0253, SB 217)
	AFM Supplement, Code No. D11	MU-2B-25/-26	FAA	01/12/1988	1	05/11/1993	BENDIX MODEL M-4D AUTOMATIC FLIGHT CONTROL SYSTEM, WITH BENDIX PITCH TRIM AND WITH AUTOMATIC RUDDER TRIM (STC No.SA561S0, SB 066/22-006)
	AFM Supplement, Code No. C2	MU-2B-15/-20/-25	FAA	01/12/1988	1	05/11/1993	BENDIX MODEL M-4C AUTOMATIC FLIGHT CONTROL SYSTEM (STC No.SA955SW, SB 066/22-006)
	AFM Supplement 6	MU-2B-25	JCAB	06/30/1997	-	-	TRIM-IN-MOTION ALERT SYSTEM (D/A No. 0256, SB 231)

MU-2 Service News

JCAB T.C.: No. 130B

DATE: May 1, 2026

Document: Airplane Flight Manual (AFM)

Doc#	Manual	Effective Model	Approval	Original/ Reissue Date	Latest		Subject
					Rev.	Issue Date	
	AFM Supplement 7	MU-2B-25	JCAB	06/30/1997	-	-	AUTOMATIC AUTOPILOT DISCONNECT SYSTEM (D/A No. 0257, SB 231)
	AFM Supplement 8	MU-2B-25	JCAB	06/30/1997	-	-	PNEUMATIC DE-ICE MONITORING SYSTEM (D/A No. 0258, SB 232)
YET 74129A	AFM	MU-2B-26	JCAB	03/03/1987	15	09/28/2021	MU-2B-26 AIRPLANE FLIGHT MANUAL
	AFM Supplement 1	MU-2B-26	JCAB	03/03/1987	1	05/10/1988	ELECTRIC PITCH TRIM SYSTEM (D/C No. 0332)
	AFM Supplement 2	MU-2B-26	JCAB	03/03/1987	-	-	STROBE LIGHT
	AFM Supplement 3	MU-2B-26	JCAB	03/03/1987	-	-	WOODWARD PROPELLER SYNCHRONIZER SYSTEM
	AFM Supplement Code No. D11	MU-2B-25/-26	FAA	01/12/1988	1	05/11/1993	BENDIX MODEL M-4D AUTOMATIC FLIGHT CONTROL SYSTEM, WITH BENDIX PITCH TRIM AND WITH AUTOMATIC RUDDER TRIM (STC No. SA561S0, SB 066/22-006)
	AFM Supplement 4	MU-2B-26	JCAB	10/20/1992	-	-	ROSEMOUNT MODEL 871CT1 SUPPLEMENTARY ICE DETECTION SYSTEM (D/A No. 0253, SB 217)
	AFM Supplement 5	MU-2B-26	JCAB	06/30/1997	-	-	PNEUMATIC DE-ICE MONITORING SYSTEM (D/A No. 0258, SB 232)
YET 69013A	AFM	MU-2B-30	JCAB	02/19/1987	16	09/28/2021	MU-2B-30 AIRPLANE FLIGHT MANUAL
	AFM Supplement 1	MU-2B-30	JCAB	02/19/1987	3	12/21/1992	BENDIX MODEL M-4C AUTOPILOT SYSTEM (D/A No. 0251, D/A No. 0332, D/A No. 0335)
	AFM Supplement 2	MU-2B-30	JCAB	02/19/1987	2	05/10/1988	ELECTRIC PITCH TRIM SYSTEM (D/A No. 0251, D/C No. 0332)
	AFM Supplement 3	MU-2B-30	JCAB	02/19/1987	-	-	STROBE LIGHT
	AFM Supplement 4	MU-2B-30	JCAB	02/19/1987	-	-	WOODWARD PROPELLER SYNCHRONIZER SYSTEM
	AFM Supplement Code No. T8	MU-2B-30	FAA	01/12/1988	-	-	BENDIX MANUAL ELECTRIC PITCH TRIM SYSTEM (STC No. SA1324SW, SB 066/22-006)
	AFM Supplement 5	MU-2B-30	JCAB	10/20/1992	-	-	ROSEMOUNT MODEL 871CT1 SUPPLEMENTARY ICE DETECTION SYSTEM (D/A No. 0253, SB217)

MU-2 Service News

JCAB T.C.: No. 130B

DATE: May 1, 2026

Document: Airplane Flight Manual (AFM)

Doc#	Manual	Effective Model	Approval	Original/ Reissue Date	Latest		Subject
					Rev.	Issue Date	
	AFM Supplement 6	MU-2B-30	JCAB	06/30/1997	-	-	TRIM-IN-MOTION ALERT SYSTEM (D/A No. 0256, SB 231)
	AFM Supplement 7	MU-2B-30	JCAB	06/30/1997	-	-	AUTOMATIC AUTOPILOT DISCONNECT SYSTEM (D/A No. 0257, SB 231)
	AFM Supplement 8	MU-2B-30	JCAB	06/30/1997	-	-	PNEUMATIC DE-ICE MONITORING SYSTEM (D/A No. 0258, SB 232)
YET 70186A	AFM	MU-2B-35	JCAB	02/19/1987	16	09/28/2021	MU-2B-35 AIRPLANE FLIGHT MANUAL
	AFM Supplement 1	MU-2B-35	JCAB	02/19/1987	3	12/21/1992	BENDIX MODEL M-4C AUTOPILOT SYSTEM (D/A No. 0251, D/A No. 0332, D/A No. 0335)
	AFM Supplement 2	MU-2B-35	JCAB	02/19/1987	2	05/10/1988	ELECTRIC PITCH TRIM SYSTEM (D/A No. 0251, D/C No. 0332)
	AFM Supplement 3	MU-2B-35	JCAB	02/19/1987	-	-	STROBE LIGHT
	AFM Supplement 4	MU-2B-35	JCAB	02/19/1987	-	-	WOODWARD PROPELLER SYNCHRONIZER SYSTEM
	AFM Supplement, Code No. D8	MU-2B-35	FAA	01/12/1988	1	05/11/1993	BENDIX MODEL M-4D AUTOMATIC FLIGHT CONTROL SYSTEM WITH BENDIX PITCH TRIM AND WITH AUTOMATIC RUDDER TRIM (STC No. SA1693SW, SB 066/22-006)
	AFM Supplement, Code No. D9	MU-2B-35	FAA	01/12/1988	1	05/11/1993	BENDIX MODEL M-4D AUTOMATIC FLIGHT CONTROL SYSTEM WITH AUTOMATIC RUDDER TRIM (STC No. 1693SW, SB 066/22-006)
	AFM Supplement, Code No. D10	MU-2B-35	FAA	01/12/1988	1	05/11/1993	BENDIX MODEL M-4D AUTOMATIC FLIGHT CONTROL SYSTEM (STC No. SA1693SW, SB 066/22-006)
	AFM Supplement 5	MU-2B-35	JCAB	10/20/1992	-	-	ROSEMOUNT MODEL 871CTI SUPPLEMENTARY ICE DETECTION SYSTEM (D/A No. 0253, SB 217)
	AFM Supplement 6	MU-2B-35	JCAB	06/30/1997	-	-	TRIM-IN-MOTION ALERT SYSTEM (D/A No. 0256, SB 231)
	AFM Supplement 7	MU-2B-35	JCAB	06/30/1997	-	-	AUTOMATIC AUTOPILOT DISCONNECT SYSTEM (D/A No. 0257, SB 231)
	AFM Supplement 8	MU-2B-35	JCAB	06/30/1997	-	-	PNEUMATIC DE-ICE MONITORING SYSTEM (D/A No. 0258, SB 232)

R

MU-2 Service News

JCAB T.C.: No. 130B

DATE: May 1, 2026

Document: Airplane Flight Manual (AFM)

Doc#	Manual	Effective Model	Approval	Original/ Reissue Date	Latest		Subject
					Rev.	Issue Date	
YET 74122A	AFM	MU-2B-36	JCAB	02/19/1987	15	09/28/2021	MU-2B-36 AIRPLANE FLIGHT MANUAL
	AFM Supplement 1	MU-2B-36	JCAB	02/19/1987	1	05/10/1988	ELECTRIC PITCH TRIM SYSTEM (D/C No. 0332, D/C No. 0259)
	AFM Supplement 1	MU-2B-36	JCAB	02/19/1987	2	09/01/1997	ELECTRIC PITCH TRIM SYSTEM (D/C No. 0332, D/C No. 0259)
	AFM Supplement 2	MU-2B-36	JCAB	02/19/1987	-	-	STROBE LIGHT
	AFM Supplement 3	MU-2B-36	JCAB	02/19/1987	-	-	WOODWARD PROPELLER SYNCHRONIZER SYSTEM
	AFM Supplement, Code No. D7	MU-2B-36	FAA	01/12/1988	1	05/11/1993	BENDIX MODEL M-4D AUTOMATIC FLIGHT CONTROL SYSTEM, WITH BENDIX PITCH TRIM AND WITH AUTOMATIC RUDDER TRIM (STC No. SA1693SW, SB 066/22-006)
	AFM Supplement, Code No. Z1	MU-2B-36	FAA	09-08-88	1	05/11/1993	SPERRY SPZ-200/STARS IVC AUTOMATIC FLIGHT CONTROL SYSTEM WITH SPERRY ELECTRIC RUDDER TRIM SYSTEM (STC No. SA1641SW, SA1723SW, 035A-985006)
	AFM Supplement 4	MU-2B-36	JCAB	10/20/1992	-	-	ROSEMOUNT MODEL 871CT1 SUPPLEMENTARY ICE DETECTION SYSTEM (D/A No. 0253, SB 217)
	AFM Supplement	MU-2B-36	JCAB	12/18/1992	1	04/06/1994	AIRESEARCH TPE331-252M ENGINES AND HARTZELL PROPELLER P/N HC-B4TN-5() / LT10282()-5.3R (STC No. SA2413SW)
	AFM Supplement	MU-2B-36	JCAB	12/18/1992	2	07/02/2013	HONEYWELL TPE331-5-252M ENGINES AND HARTZELL PROPELLER P/N HC-B4TN-5() / LT10282()-5.3R (STC No. SA2413SW)
	AFM Supplement 5	MU-2B-36	JCAB	06/30/1997	-	-	PNEUMATIC DE-ICE MONITORING SYSTEM (D/A No. 0258, SB 232)
	AFM Supplement 6	MU-2B-36	JCAB	09/01/1997	-	-	BENDIX MODEL M-4C AUTOPILOT SYSTEM (D/A No. 0259)
	AFM Supplement 7	MU-2B-36	JCAB	09/01/1997	-	-	TRIM-IN-MOTION ALERT SYSTEM (D/A No. 0259, SB 231)
	AFM Supplement 8	MU-2B-36	JCAB	09/01/1997	-	-	AUTOMATIC AUTOPILOT DISCONNECT SYSTEM (D/A No. 0259, SB 231)

MU-2 Service News

JCAB T.C.: No. 130B

DATE: May 1, 2026

Document: :Pilot Check List (PCL)

Doc#	Manual	Effective Model	Approval	Original/ Reissue Date	Latest		Note
					Rev.	Issue Date	
YET 06244	PCL	MU-2B	FAA*	12/25/2006	E	11/19/2024	R
YET 06245B	PCL	MU-2B-10	FAA*	12/25/2006	B	05/06/2010	
YET 06246B	PCL	MU-2B-15	FAA*	12/25/2006	B	05/06/2010	
YET 06248	PCL	MU-2B-25	FAA*	12/25/2006	E	11/19/2024	R EXCEPT S/N 313SA
YET 06249	PCL	MU-2B-26	FAA*	12/25/2006	E	11/19/2024	R EXCEPT S/N 349SA
YET 06250	PCL	MU-2B-30	FAA*	12/25/2006	E	11/19/2024	R
YET 06251	PCL	MU-2B-35	FAA*	07/18/2006	F	11/19/2024	R
YET 06252	PCL	MU-2B-36	FAA*	07/18/2006	F	11/19/2024	R EXCEPT S/N 689SA - 696SA
YET 06252-1	PCL	MU-2B-36	FAA*	not issued	F	11/19/2024	R WITH TPE331-5-252M ENGINES S/N 689SA - 696SA

MU-2 Service News

JCAB T.C.: No. 130B

DATE: May 1, 2026

Document: Pilot's Operating Manual (POM)

Doc#	Manual	Effective Model	TC	Original/ Reissue Date	Latest			Note
					Rev.	Temp. Rev.	Issue Date	
YET 67025A	POM	MU-2B	JCAB	12/10/1987	3	-	09/10/1997	ORIG(10/01/1966) TR 2-1, 3-1, 3-2, 4-1
YET 87236	POM	MU-2B-10	JCAB	11/30/1987	3	-	09/10/1997	TR 2-1, 3-1, 3-2, 4-1
YET 87237	POM	MU-2B-15	JCAB	11/20/1987	3	-	09/10/1997	TR 2-1, 3-1, 3-2, 4-1
YET 68134A	POM	MU-2B-20	JCAB	11/10/1987	4	-	02/20/1998	ORIG(07/01/1968) TR 2-1, 3-1, 3-2, 3-3, 4-1
YET 72067A	POM	MU-2B-25	JCAB	10/30/1987	3	-	09/10/1997	ORIG(07/01/1972) TR 2-1, 3-1, 3-2, 3-3, 4-1
YET 74130A	POM	MU-2B-26	JCAB	09/01/1987	5	-	09/10/1997	ORIG(09/01/1974) TR 2-1, 3-1, 3-2, 3-3, 4-1
YET 69224A	POM	MU-2B-30	JCAB	10/01/1987	3	-	09/10/1997	ORIG(10/01/1969) TR 2-1, 3-1, 3-2, 3-3, 4-1
YET 70187A	POM	MU-2B-35	JCAB	07/01/1987	3	-	09/10/1997	ORIG(06/01/1971) TR 2-1, 3-1, 3-2, 3-3, 4-1
YET 74123A	POM	MU-2B-36	JCAB	06/01/1987	3	-	09/10/1997	ORIG(09/01/1974) TR 2-1, 3-1, 3-2, 3-3, 4-1

R R R R R R

MU-2 Service News

JCAB T.C.: No. 130B

DATE: May 1, 2026

Document: Maintenance Manual (MM)

Doc#	Manual	Effective Model	TC	Original/ Reissue Date	Latest			Note
					Rev.	Temp. Rev.	Issue Date	
YET 67164	MM	MU-2B	JCAB	10/01/1967	19	-	12/27/1999	TR 2-1 thru 2-9, 3-1 thru 3-4, 4-1 thru 4-15, 5-1A, 5-2 thru 5-5, 6-1 thru 6-3, 9-1, 14-1 (INCLUDES WIRING DIAGRAM MANUAL)
YET 67027	MM	MU-2B-10	JCAB	08/01/1967	22	-	12/27/1999	TR 2-1 thru 2-3, 3-2, 4-1 thru 4-4, 4-6 thru 4-11, 5-1A, 5-2 thru 5-3, 9-1, 14-1 (INCLUDES WIRING DIAGRAM MANUAL)
YET 68101	MM	MU-2B-15	JCAB	04/01/1968	4	-	12/27/1999	TR 2-1 thru 2-3, 3-2, 4-1 thru 4-4, 4-6 thru 4-11, 5-1A, 5-2 thru 5-3, 9-1, 14-1 (INCLUDES WIRING DIAGRAM MANUAL)
YET 68035	MM	MU-2B-20	JCAB	04/01/1968	19	-	12/27/1999	TR 2-1 thru 2-3, 2-4A, 2-5 thru 2-10, 3-1 thru 3-5, 4-1 thru 4-13, 5-1A, 5-2 thru 5-5, 6-1 thru 6-5, 8-1, 9-1, 9-2, 14-1
YET 71370	MM	MU-2B-25	JCAB	12/01/1971	15	-	12/27/1999	TR 2-1 thru 2-3, 2-4A, 2-5 thru 2-10, 3-1 thru 3-5, 4-1 thru 4-13, 5-1A, 5-2 thru 5-5, 6-1 thru 6-5, 8-1, 8-2, 9-1, 9-2, S1-1
YET 74132	MM	MU-2B-26	JCAB	05/01/1974	14	-	12/27/1999	TR 2-1 thru 2-3, 2-4A, 2-5 thru 2-10, 3-1 thru 3-5, 4-1 thru 4-14, 5-1A, 5-2 thru 5-5, 6-1 thru 6-5, 8-1, 9-1, 9-2
YET 69016	MM	MU-2B-30	JCAB	07/01/1969	20	-	12/27/1999	TR 2-1 thru 2-3, 2-4A, 2-5A, 2-6 thru 2-11, 3-1 thru 3-5, 4-1 thru 4-15, 5-1A, 5-2 thru 5-5, 6-1 thru 6-5, 9-1, 9-2, 11-1
YET 70191	MM	MU-2B-35	JCAB	01/01/1971	17	-	12/27/1999	TR 2-1 thru 2-3, 2-4A, 2-5A, 2-6 thru 2-11, 3-1 thru 3-5, 4-1 thru 4-15, 5-1A, 5-2 thru 5-5, 6-1 thru 6-5, 9-1, 9-2, 11-1
YET 74125	MM	MU-2B-36	JCAB	01/01/1971	14	-	12/27/1999	TR 2-1 thru 2-3, 2-4A, 2-5A, 2-6 thru 2-11, 3-1 thru 3-5, 4-1 thru 4-15, 5-1A, 5-2 thru 5-5, 6-1 thru 6-5, 9-1, 9-2, 11-1

MU-2 Service News

JCAB T.C.: No. 130B

DATE: May 1, 2026

Document: Wiring Diagram Manual (WDM)

Doc#	Manual	Effective Model	TC	Original/ Reissue Date	Latest			Note
					Rev.	Temp. Rev.	Issue Date	
YET 71288	WDM	MU-2B-20	JCAB	07/01/1971	-	-	07/07/1993	
YET 71371	WDM	MU-2B-25	JCAB	12/01/1971	5	-	08/27/1999	
YET 74133	WDM	MU-2B-26	JCAB	05/01/1974	2	-	08/27/1999	
YET 71289	WDM	MU-2B-30	JCAB	07/01/1971	4	-	08/27/1999	
YET 70206	WDM	MU-2B-35	JCAB	04/01/1971	5	-	08/27/1999	
YET 74126	WDM	MU-2B-36	JCAB	05/01/1974	2	-	08/27/1999	

Document: Aircraft Inspection and Maintenance Requirements Manual (MRM)

Doc#	Manual	Effective Model	TC	Original/ Reissue Date	Latest			Note
					Rev.	Temp. Rev.	Issue Date	
MR-0178-2	MRM	MU-2B/-10 /-15/-20/-25 /-26/-26A/-40	JCAB & FAA	07/02/1976	1	-	07/10/2017	TR 1 thru 3 R
MR-0179-2	MRM	MU-2B-30 /-35/-36/-36A /-60	JCAB & FAA	07/02/1976	1	-	07/10/2017	TR 1 thru 3 R

Document: Structural Repair Manual (SRM)

Doc#	Manual	Effective Model	TC	Original/ Reissue Date	Latest			Note
					Rev.	Temp. Rev.	Issue Date	
YET72035A	SRM	ALL	JCAB & FAA	01/01/1997	2	-	01/25/2002	ORIG(01/01/1972) TR 1-1 thru 1-6, 2-1 thru 2-2, 3-1, 4A-1 thru 4A-11, 4B-1 thru 4B-14, 5-1 thru 5- 8, 6-1 thru 6-2, 6-3A R

MU-2 Service News

JCAB T.C.: No. 130B

DATE: May 1, 2026

Document: Parts Catalog (PC)

Doc#	Manual	Effective Model	TC	Original/ Reissue Date	Latest			Note	
					Rev.	Temp. Rev.	Issue Date		
YET 67165	PC	MU-2B	JCAB	09/01/1967	12	-	04/16/2001	TR 2-1 thru 2-23	R
YET 67028	PC	MU-2B-10	JCAB	05/01/1967	13	-	04/16/2001	TR 2-1 thru 2-8	
YET 68170	PC	MU-2B-15	JCAB	10/01/1968	12	-	04/16/2001	TR 2-1 thru 2-8	
YET 68036B	PC	MU-2B-20	JCAB	09/01/2000	1	-	04/16/2001	ORIG(05/01/1968) TR 2-1 thru 2-28, 2-19A, 2-20A, 2-21 thru 2-53	R
YET 72092A	PC	MU-2B-25	JCAB & FAA	06/01/2000	1	-	04/16/2001	ORIG(08/01/1974) TR 2-1 thru 2-28, 2-19A, 2-20A, 2-21 thru 2-46	R
YET 74134A	PC	MU-2B-26/-26A	JCAB & FAA	03/01/2000	1	-	04/16/2001	ORIG(08/01/1974) TR 2-1 thru 2-16, 2-17A, 2-18A, 2-19 thru 2-49	R
YET 69019	PC	MU-2B-30	JCAB	10/01/1969	14	-	04/16/2001	TR 2-1 thru 2-14, 2-15A, 2-16A, 2-17 thru 2-39	R
YET 70193A	PC	MU-2B-35	JCAB & FAA	07/01/1999	1	-	04/16/2001	ORIG(08/01/1971) TR 2-1 thru 2-13, 2-14A, 2-15A, 2-16 thru 2-36	R
YET 74127A	PC	MU-2B-36/-36A	JCAB & FAA	06/01/1999	1	-	04/16/2001	ORIG(08/01/1974) TR 2-1 thru 2-20, 2-21A, 2-22A, 2-23 thru 2-46	R

THIS PAGE INTENTIONALLY LEFT BLANK